



INSTRUMENT USED - TOPCON GTS-3
 ANGULAR ERROR - 2" PER POINT
 TRAVERSE CLOSURE - 1/79564
 LEAST SQUARES ADJUSTMENT

LEGEND
 1/2" REBAR SET
 PIPE FOUND
 COMPUTED POINT

U.S.A. (THURMOND L)

U.S.A. (THURMOND LAKE)

N 89°56'W 827.04'
 78.00'

1.68 AC
 MAP CHECK
 1/324764
 (A41)

1.49 AC
 MAP CHECK
 1/282240
 (A42)

1.26 AC
 MAP CHECK
 1/420523
 (A43)

1.10 AC
 MAP CHECK
 1/313822
 (A44)

1.08 AC
 MAP CHECK
 1/210924
 (A45)

1.07 AC
 MAP CHECK
 1/37281
 (A46)

1.06 AC
 MAP CHECK
 1/458052
 (A47)

1.06 AC
 MAP CHECK
 1/453449
 (A48)

1.05 AC
 MAP CHECK
 1/452846
 (A49)

1.04 AC
 MAP CHECK
 1/23926
 (A50)

1.70 AC
 MAP CHECK
 1/331134
 (A74)

2.01 AC
 MAP CHECK
 1/78842
 (A109)

2.07 AC
 MAP CHECK
 1/254796
 (A114)

2.78 AC
 MAP CHECK
 1/460824
 (A110)

1.85 AC
 MAP CHECK
 1/53404
 (A113)

1.51 AC
 MAP CHECK
 1/473919
 (A112)

1.84 AC
 MAP CHECK
 1/850539
 (A111)

3.02 AC
 MAP CHECK
 1/303777
 (A108)

2.00 AC
 MAP CHECK
 1/43434
 (A76)

2.00 AC
 MAP CHECK
 1/164616
 (A75)

1.83 AC
 MAP CHECK
 1/31134
 (A74)

1.78 AC
 MAP CHECK
 1/201269
 (A73)

1.52 AC
 MAP CHECK
 1/350729
 (A72)

1.27 AC
 MAP CHECK
 1/350729
 (A71)

1.27 AC
 MAP CHECK
 1/350729
 (A70)

1.27 AC
 MAP CHECK
 1/350729
 (A70)

1.27 AC
 MAP CHECK
 1/350729
 (A70)

1.27 AC
 MAP CHECK
 1/350729
 (A70)

1.27 AC
 MAP CHECK
 1/350729
 (A70)

1.27 AC
 MAP CHECK
 1/350729
 (A70)